




**IDEAL INDUSTRIES INC.
TECHNICAL MANUAL - SUPPLEMENT
MODEL 61-791**

The Service Information provides the following:

- *This is a Supplemental Manual to Megger's DM220 Service Manual and is intended for Performance test and Calibration requirements only.*
- Precautions and safety information
- Specifications
- Performance test procedure
- Calibration and calibration adjustment procedure
- Basic maintenance (replacing the battery and fuses)



Form number: TM61791-Supplement
Revision: 1. Date: August 2004

TABLE OF CONTENTS

Title	Page #
Introduction	1
Precautions and Safety Information	1
Safety Information	1
Performance Verification	2
Table 1 Verification 61-791	2
Calibration	3
Replacing the Battery	4
Replacing Fuses	4

Introduction

Warning

To avoid shock or injury, do not perform the verification tests or calibration procedures described in this manual unless you are qualified to do so. The information provided in this document is for the use of qualified personnel only.

Caution

The 61-791 contains parts that can be damaged by static discharge. Follow the standard practices for handling static sensitive devices.

*For additional information about IDEAL INDUSTRIES and its products, and services, visit IDEAL INDUSTRIES web site at:
www.idealindustries.com*

SAFETY

Review the following safety precautions to avoid injury and prevent damage to this product or any products connected to it. To avoid potential hazards, use the product only as specified.

It is recommended that you read through the Operation or User manual before starting. Not all Caution, Warning, or Danger precautions are listed in this manual.

CAUTION.

These statements identify conditions or practices that could result in damage to the equipment or other property.

WARNING.

These statements identify conditions or practices that could result in personal injury or loss of life.

Specific precautions

Use proper Fuse. To avoid fire hazard, use only the fuse type and rating specified for this product.

Do not operate without covers. To avoid personal injury, do not apply any voltage or current to the product without the covers in place.

Electric overload. Never apply a voltage to a connector on the product that is outside the range specified for that connector.

Avoid electric shock. To avoid injury or loss of life, do not connect or disconnect probes or test leads while they are connected to a voltage source.

Avoid electric shock. To avoid injury or loss of life, do not come in contact with tested material or probes while the Test Button is pressed. High Voltage potentials are present during Insulation Tests..

Do not operate in wet/damp conditions. To avoid electric shock, do not operate this product in wet or damp conditions.

PERFORMANCE VERIFICATIONS

Perform the following analysis, if the meter conforms to the limits listed in Table 1 the meter is functioning correctly. If the meter does not conform to any of the listed limits, the calibration procedure must be performed.

Performance Verification Preparation

Set-up requirements:


1. Prepare all required equipment and standards prior to test
 2. The **Test Button** is only needed for insulation test or to **ZERO** lead resistance
 3. Remove bottom cover and using a calibrated meter to ensure the battery measures $8.0V \pm 1 V$
If battery voltage is $<8V$, replace batteries before beginning.
 4. Simulated test leads with a value of $0.1\Omega \pm 10m\Omega$ is required for Calibration of Ω /Zero Function
- ** Due to auto-ranging circuit thresholds, either one or no digits may appear after the decimal place on the 100M Ω test; Example { "98" or "98.2" } may be displayed.

Check safety related VR37 resistors for correct type

Check fuse is 500mA (type F) 10KA rated

Check case, leads, display and etc, for any defects.

**Table 1 Performance Verification
Model 61-791**

Function Setting /Range	Apply	Reading	Specification
Default Voltmeter			
Ω /Zero	240V AC	238 to 242	[$\pm 1\% \pm 0$ digits]
Ω /Zero	240V DC	226 to 254	[$\pm 1\% \pm 10$ digits]
Ω /Zero	50V AC	46 to 54	[$\pm 2\% \pm 3$ digits]
Continuity 	1 Ω	Buzzer sounds	Not specified
Resistance			
Ω /Zero	Simulated leads	.08 to .12	[$\pm 0.02\Omega + 0.05$ per lead]
Ω /Zero	0 Ω	-0.02 to +0.02	[$\pm 0.02\Omega$]
Ω /Zero	9 Ω	8.72 to 9.28	[$\pm 3\% \pm 1$ digits]
Ω /Zero	12 Ω	11.3 to 12.7	[$\pm 5\% \pm 1$ digits]
Ω /Zero	90 Ω	85.4 to 94.6	[$\pm 5\% \pm 1$ digits]
Ω /Zero	90 Ω	20.2mA to 25.8mA	Source check
Ω /Zero	1 Ω	202mA to 258mA	Source check
Insulation			
M Ω , 250V	500k Ω	>255Vdc	Source Check
M Ω , 500V	500k Ω	>503Vdc	Source Check
M Ω 1000V	1M Ω	>1005Vdc	Source Check
Check on each Voltage range	100k Ω	0.08 to 0.12	Not specified
	1M Ω	0.97 to 1.03	[2.5%]
	9M Ω	8.77to 9.23	[2.5%]
	100M Ω	95.5 to 105	[4.5%]
	500M Ω	360 to 640	[28%]
M Ω , 250V	500M Ω	<323V	Source Check
M Ω , 500V	500M Ω	<645V	Source Check
M Ω 1000V	500M Ω	<1290V	Source Check
Check on each Voltage range	0M Ω	1.3mA to 1.95mA	Source Check

CALIBRATION

Calibration Preparation

Required Equipment

The class of calibrator or equipment should have an accuracy that exceeds, by an expectable ratio, the accuracy of the instrument under test.

Required fixed resistors: 0 Ω , 9 Ω , 12 Ω , 90 Ω , 500K Ω , 8M Ω , 100M Ω

Simulated Test leads. With a total resistance of <.1 Ω \pm 10m Ω or .05 Ω per simulated lead.

Calibration Procedure

It is recommended that all IDEAL meters undergo calibration checkup on an annual bases.

61-791 Calibration Procedure.

Calibration

Voltage Set-up

- 1) Set the Function/Range Switch to the “ Ω ” position.
- 2) Set the output of the AC calibrator for 240V and connect it to the “+” and “-” input terminals.
- 3) Adjust [V] R30 until the display reads 240V \pm 1 digit.
- 4) Apply 240V DC and Check for a display of 240V \pm 10 digit

Note: *Meter will beep while Voltage is present.*

Voltage sourcing test and [M Ω] adjustment

- 5) Set the Function/Range Switch to M Ω 500V
- 6) Apply a 500K Ω Load to unit, measured Vdc across load should be >504V
- 7) Apply a 100M Ω Load to unit, measured Vdc across load should be >640V
- 8) Apply an 8M Ω Standard Load to unit
- 9) Adjust [M Ω], R100 for a reading of 8.00M Ω \pm 5 digits


Ohms Zero Adjustment:

- 1) Place unit in the Ω /Zero function.
- 2) Connect the Simulated test leads to unit
- 3) Adjust [0 Ω], R159 for a reading of 0.10 Ω
- 4) Press button to set reading to zero
- 5) Confirm 0.00 \pm 3 digits

Ohms Adjustment,

- 1) Place unit in the Ω /Zero function.
- 2) Connect a 9 Ω standard to unit
- 3) Adjust [Ω], R61 for a reading of 9 Ω \pm 3 digits
 - a. Connect 12 Ω check reading is between 11.6 Ω to 12.4 Ω
 - b. Connect 90 Ω check reading is between 86.0 Ω to 94.0 Ω

Buzz check

- Place unit in the  (continuity) position.
- Short test leads and confirm buzzer operation.

Battery Replacement

1. Disconnect the test leads from any circuit under test and turn off meter.
2. Release screw from the bottom end of case cover. (Screw is secured to case)
3. Remove the 6 AA batteries from battery adapter.
4. Install new 6 new AA batteries into adapter, observing proper polarity of battery.
(Alkaline batteries are recommended.)
6. Install bottom case cover and secure with screws.

Replacing Fuse

1. Disconnect the test leads and turn the range switch to "OFF".
2. Release screw from the bottom end of case cover. (Screw is secured to case)
3. Check fuse with a digital multimeter with a source current $< 10\text{mA}$ in low resistance range.
Replace fuse with a 500 mA (type F), 10KA rated fuse.
4. Install bottom cover and secure with screw.

